

HOE ULI WAY

LOT 80 18,005 SQ. FT.

NOTES:

- 1) No boundary encroachments were found.
- 2) No violations of County zoning set-back codes were found.
- The distances shown between the property lines & the features, shown hereon, are based on selected found boundary monuments & acceptable tolerances for properties of this type.
- 4) The features, shown hereon, were located by an actual survey performed on the ground on April 5th, 2022.
- 5) See accompanying report pertaining to setbacks and encroachments.
- 6) CRM = Concrete, Rock & Masonry Wall

Setback Lines are shown from current data, but should be verified by builder. The description on this plat was provided to us by the client, and does not guarantee ownership, and should be compared to your Deed, Abstract or Certificate of Title. All building restrictions, building lines and easements may or may not be shown, check your Deed, Abstract, Title Report, and local ordinances, no responsibility is assumed by Surveyor. Compare all points before building by same and report any discrepancy at once. Dimensions are shown in feet and decimal parts thereof, no dimension is to be assumed by scaling.

NOTE: BASIS OF AZIMUTH DERIVED USING HEMISPHERE GPS RTK SYSTEM

NOTE: ALL CORNERS ARE FOUND IRON PIPES UNLESS OTHERWISE NOTED

NOTE: ALL AZIMUTHS & DISTANCES ARE SHOWN & MAPPED HEREON IN A CLOCKWISE DIRECTION I, Thomas G. Pattison, do hereby certify that this map is an accurate representation of a survey as made on the ground, by me, or under my direct supervision and that there are no apparent or visible encroachments or easements, known to me, except as shown and mapped hereon.



THOMAS G. PATTISON April 14th, 2022 Hawaii License No. 10743

PATTISON LAND SURVEYING

P.O. Box 384569 • Waikoloa Hawaii • 96738 • Office 808.327.9439 •



DRAIN

HOE ULI WAY

LOT 80 18,005 SQ. FT.

NOTES:

1) No boundary encroachments were found. 2) No violations of County zoning set-back codes were found.

- 3) The distances shown between the property lines & the features, shown hereon, are based on selected found boundary monuments & acceptable tolerances for properties of this type.
- 4) The features, shown hereon, were located by an actual survey performed on the ground on April 5th, 2022.
 5) See accompanying report pertaining to setbacks and encroachments.
 6) CRM = Concrete, Rock & Masonry Wall

wn from current data, but sh t was provided to us by the The e compared to your Deed, Abstract or Certificate building lines and easements may or may not be ct, Title Report, and local ordinances, no respons . mpare all points before building by same and r ensions are shown in feet and decimal parts the ed by scaling.

NOTE: BASIS OF AZIMUTH DERIVED USING HEMISPHERE GPS RTK SYSTEM

NOTE: ALL CORNERS ARE FOUND IRON PIPES UNLESS THERWISE NOTED

TE: ALL AZIMUTHS & PPED HEREON IN A CKWISE DIRECTION

PATTISON LAND SURVEYING

I, Thomas G. Pattison, do hereby certify that this map is an accurate representation of a survey as made on the ground, by me, or under my direct supervision and that there are no apparent or visible encroachments or easements, known to me, except as shown and mapped hereon.



THOMAS G. PATTISON April 14th, 2022 Hawaii License No. 10743

P.O. Box 384569 Waikoloa Hawaii 96738 •Office 808.327.9439•